$\label{lem:Bremer} \mbox{From:Bremer, Thomas $<$tbremer@Register-IRI.com>$ on behalf of Technical }$

<technical@Register-IRI.com>

Sent:05 June 2015 00:31

To: Lupu, Marin

Cc:technical@register-iri.com; Trull, Albert; Sea Athena - Data; Sea Athena

Vessel Control Group; Blackburn, Mike; Investigations; Kong, Davis

Subject: RE: MV SEA ATHENA - possible Off-spec LSMGO

Attachments: MSAdvisory 7-14 (Guidance re Non-availability of Compliant Fuel-US &

Can...pdf; MN-2-013-8.doc

Good Day Capt. Lupu,

Your below is duly noted. This email serves as official notification to the Administrator concerning the

LS gas oil sulfur content in excess of .1% and may be presented to port state control authorities, if

needed.

In accordance with U.S. regulations, a fuel oil non-availability report (FONAR) must be submitted as soon

as possible but at all times prior to entering the ECA. This process is detailed in the attached Marine

Safety Advisory 7-14. Kindly ask that you confirm when this notice is submitted. The declaration of

sulfur content from the bunker supplier, along with the fuel oil changeover procedures must be readily

available on board for examination by the port state control authority, if requested. In addition, please

advise the plan for supplying the vessel with compliant fuel oil.

Our Investigations Dept. may revert with any additional information needed.

Best Regards,

Thomas Bremer

International Registries, Inc.

140 Broadway, Suite 4430

New York, NY 10005

Tel: 646-400-5910

Fax: 212-248-7290

Cell: 832-306-9009

From: Lupu, Marin [mailto:Marin.Lupu@vships.com]

Sent: Thursday, June 04, 2015 6:46 PM

To: Bremer, Thomas

Cc: Technical; Trull, Albert; Sea Athena - Data; Sea Athena Vessel Control Group;

Blackburn, Mike

Subject: MV SEA ATHENA - possible Off-spec LSMGO

Dear Thomas,

We are writing to inform Flag State that the LS Gas Oil which was supplied in China before sailing might

be off-spec; namely the Sulphur content shows 0.32% (mm) i/o 0.1% (mm) as per ECA current

requirements. A very recent retesting of company sample showed the same Sulphur content as per

initial analysis.

Having said that we $\$ asking for your suggestions. For info, per master reports the vessel has another 10

hours before she will enter ECA where she will change over to LSGO.

With best regards

Capt. Marin Lupu, MBA, MNI Snr. MSQ Superintendent V.Ships UK Ltd As agents only

Direct: +44(0)1413057807

Switchboard: +44(0)1412432435

Mobil: +44(0)7768553803

Email: marin.lupu@vships.com

Website: www.vships.com

V.SHIPS UK LTD AS MANAGERS AND AGENTS ONLY, FOR AND ON BEHALF OF OWNERS ATHENA SHIPOWNING INC AND THE VESSEL "SEA ATHENA".

This email is confidential and intended solely for the use of the individual to whom it is

addressed. If you are not the intended recipient, be advised that you have received this email in

error and that any use, dissemination, forwarding, printing or copying of this email is strictly

prohibited. If you have received this email in error please contact the sender.

? We only print the emails we really need to

This email has been scanned for all viruses by the MessageLabs Email Security System.